



OPERATOR MODEL
"RSW" (Series 2000)

RSW (SERIES 2000)

PowerMaster

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
1	ONE	HOUSING		4004	
2	ONE	TOP COVER UPPER DRIVE FRAME		4006	
3	ONE	UPPER DRIVE FRAME		4008	
4	ONE	LOWER DRIVE FRAME		4009	
5	ONE	BOTTOM PAN		4005	
6	ONE	ELECTRIC PLATE		4001	
7	ONE	CONTROL ARM WELDMENT		4020	
8	ONE	CONTROL ARM EXTENSION		707-1	
9	ONE	FRONT COVER		4007	
10	ONE	CAPACITOR STRAP		1104	
11	ONE	UPPER CHAIN ADJUSTMENT PLATE		2214	
12	ONE	LOWER CHAIN ADJUSTMENT PLATE		2215	
13	ONE	LOOP DETECTOR BRACKET (OPTIONAL)		3704	
14A	ONE	LIMIT SWITCH BRACKET, OR		1106	
14B	ONE	MINI LIMIT SWITCH BRACKET		4022	
15	ONE	JUNCTION BOX COVER		4002	
16	TWO	CONTROL ROD FITTING (PIPE KNUCKLE)		2212	
17	ONE	ANTI-PINCH DISC		733	
18	ONE	TERMINAL STRIP BRACKET		4017	
19	ONE	OUTPUT SHAFT		4010	
20	ONE	SENSITIVITY SHAFT		4011	
21	TWO	CONTROL ROD		2221	
22	ONE	SPLICE BAR-CONTROL ROD		4012	
23	ONE	DOOR BRACKET		2822	
24	ONE	3/16" SQUARE KEY		SK316X1.375	
25	ONE	1/4" SQUARE KEY		SK14X1.375	
26	ONE	MOTOR PULLEY 1 1/2" X 1/2" BORE		9002	
27					
28					
29	ONE	DRIVE SHEAVE 7 1/2" X 5/8" (HUB BORE)		9011	
30	ONE	V-BELT		4L-340	
31	THREE	LIMIT COLLAR		SC100-L	
32	ONE	SPROCKET 48B14X1		7331	
33	THREE	RSW CLUSTER SPROCKET		7332	
34	ONE	STANDARD CLUSTER SPROCKET 48B14321		7328	
35	ONE	REDUCTION SPROCKET 41B32-1" X 1/4"		7302	
36	FOUR	DRIVE CHAIN WITH CONNECTING LINK		RC65X41P	
37	ONE	FINAL DRIVE CHAIN		RC41X41	
38	THREE	1" FLANGE BEARING		FB-1000	

RSW (SERIES 2000)

PowerMaster

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
39	ONE	5/8" FLANGE BEARING		FB-625	
40	FOUR	1" PLAIN BEARING		PBO-1011275	
41	TWO	3/8" PLAIN BEARING		PBO-376262	
42					
43					
44	ONE	MOTOR		PSC-50150	
45	ONE	PC CONTROL BOARD		GSMCB02	
46	ONE	8 PIN WIRING HARNESS		8P-HARN	
47	TWO	10 PIN WIRING HARNESS		10P-HARN	
48	ONE	14 POSITION TERMINAL STRIP		TS-114	
49	ONE	4 POSITION TERMINAL STRIP		TS-04	
50	ONE	2 POSITION TERMINAL STRIP		TS-02	
51	ONE	4 POSITION R/C TERMINAL STRIP		R/C-TS-04	
52	ONE	TRANSFORMER		TU1-24-40VA	
53	ONE	CAPACITOR		CAP-70220	
54	ONE	FUSE HOLDER		FH-300-20	
55	ONE	10 AMP FUSE		F-250-10	
56	ONE	ON/OFF POWER SWITCH		2GK51-73	
57A	THREE	LIMIT SWITCH, OR		LSAT	
57B	THREE	MINI LIMIT SWITCH		LS-D44	
58	FOUR	1/4" LIMIT SWITCH SPACER FOR MINI LIMIT SWITCHES (NOT SHOWN)		60195	
59					
60	ELEVEN	1" E-RING		SE-98-01	
61	AS REQ	1" SHIM		1X016	
62	AS REQ	1" SHIM		1X050	
63	FOUR	5/8" SHIM		625X016	
64	FIVE	5/16" X 1-5/8" ROLL PIN		R312X1.625	
65					
66	TWO	SOCKET SET SCREW		1410SSC	
67	SEVEN	SOCKET SET SCREW		3105SSC	
68	FOUR	SQUARE HEAD SET SCREW		SQ1420X625	
69	FOUR	PAN HEAD MACHINE SCREW		0610MSP	
70A	TWO	TRUSS HEAD MACHINE SCREW, OR		0636MST	
70B	TWO	PAN HEAD MACHINE SCREW (FOR MINI LIMIT SWITCHES) NOT SHOWN		0432MSP	
71	THREE	ROUND HEAD MACHINE SCREW		1406MSR	
72	THREE	HEX WASHER HEAD TYPE B, SHEET METAL SCREW		0804BSW	
73	FOUR	HEX WASHER HEAD TYPE B, SHEET METAL SCREW		1008BSW	
74	ONE	HEX WASHER HEAD MACHINE SCREW (GREEN)		1106MSW(G)	

RSW (SERIES 2000)

PowerMaster

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
75	24	HEX WASHER HEAD TYPE B, SHEET METAL SCREW		3108BW	
76	TWO	HEX HEAD BOLT		1410BHT	
77	TWO	HEX HEAD BOLT		3108BHT	
78	FOUR	HEX HEAD BOLT		3712BHT	
79	ONE	HEX HEAD BOLT		3716BHT	
80	TWO	HEX HEAD TAP BOLT		3732BHT	
81	FOUR	2" U-BOLT		2"U3/8-16	
82					
83	SIX	SERRATED FLANGE HEX NUT		06NR	
84	TWO	SERRATED FLANGE HEX NUT		11NR	
85	TWO	SERRATED FLANGE HEX NUT		14NR	
86	TWO	SERRATED FLANGE HEX NUT		31NR	
87	TEN	HEX NUT		37NF	
88	TWO	HEX MACHINE SCREW NUT (FOR MINI SWITCHES) NOT SHOWN		04NH188	
89	TWO	FLAT WASHER		06WSAE	
90	24	FLAT WASHER		31WSAE	
91	TWELVE	FLAT WASHER		37WSAE	
92	TWO	LOCK WASHER (FOR MINI LIMIT SWITCHES) NOT SHOWN		04WS	
93	ONE	LOCK WASHER		14WS	
94	THREE	LOCK WASHER		37WS	
95	ELEVEN	LOCK WASHER			
96				HK-3816	
97	TWO	PHENOLIC KNOB		SR-100	
98	ONE	CONTROL ARM SEAL RING			
99				PSO-14	
100	SIX	PLASTIC STAND OFF		1624-00411	
101	TWO	RIVET		SD-46BS	
102	EIGHT	RIVET			
103					
104	THREE	1/2" GROMMET		G-50	
105	ONE	7/8" GROMMET		G-87	