



OPERATOR MODEL
"WBG (P5000)"

WBG (P5000)

PowerMaster

ITEM	QTY.	DESCRIPTION	PARTS #	LIST PRICE
1	One	Main housing weldment	900	
2	One	Cover	901-1	
3	One	Side door	987	
4	One	Arm flange weldment	942	
5	One	Electric plate	970	
6	One	Cluster weldment	1035	
7	One	Drive plate weldment	1029	
8	One	Pressure plate	1030	
9	One	Limit switch mounting bracket	973	
10	One	Switch panel	971	
11	One	Accessory plate assembly	969	
12				
13	One	Drive shaft weldment	915	
14	One	Intermediate shaft	906	
15	One	Lower control arm	904	
16	One	Upper control arm	914	
17	One	Drive link	935	
18	One	3/16" Square key	SK316X1.250	
19	One	3/16" Square key	SK316X1.375	
20	Two	1/4" Square key	SK14X1.250	
21	One	3/8" Square key	SK375X1.125	
22	One	Motor pulley	AS2062	
23				
24	Two	Clutch disc	1034CSW	
25	One	7-1/2" "A" drive sheave	AS-7558	
26	One	V-Belt	4L-270	
27	One	Gear reducer	LIM-55	
28	One	Intermediate sprocket	7313	
29	One	Drive chain	50X41	
30	Two	1" Four bolt flange bearing	UCF20516	
31	Two	1-1/4" Two bolt flange bearing	UCFL20720	
32	Three	Limit collar	SC100-L	
33	Four	Clutch spring	9-1204-21	
34	Two	3/4" Plain bearing	PB07510050	
35	Two	Bearing spacer	941	
36	One	Motor	10082	
37	One	Control printed circuit board	BARCON1	
38	One	or control board/timer board (as required)	PRB3/ACT	
39	One	12 Pin wiring harness	12P-HARN	
40	One	2 Amp resettable fuse	REY0022	
41	One	Transformer	TU1-2440VA	
42	One	14 Position terminal strip	TB-114	
43	One	Timer toggle switch	CB201-37	
44	One	On/off switch (DPDT) (set)	2GK51-73	
45	One	Open/close switch (set)	6GM5B-78	

WBG (P5000)

PowerMaster

ITEM	QTY.	DESCRIPTION	PARTS #	LIST PRICE
46	One	Double limit switch	LS-DAT#6	
47	One	Single limit switch	LS-AT#2	
48	One	Straight connector (set)	501-DC2	
49	Two	Male connector	4-PIN-MCON	
50	Two	Female connector	4-PIN-FCON	
51	One	15A, 120V Incoming power switch	W/RECEPTACLE	
52	One	1Ø Overload reset switch (set)	MB-07	
53	One	9 Pin male connector	9P-MCON	
54	One	9 Pin female connector	9P-FMCON	
55	One	Interlock switch	IS#10	
56	Two	Hex washer head (8-32) machine screw	0808MSW	
57	Two	Hex washer head machine screw (green)	1106MSW	
58	Nine	Socket set screw	3105SSC	
59	Four	Square head set screw	SQ51618X675	
60	Two	Square head set screw	SQ51618X1	
61	Four	Socket set screw	1404SSC	
62	Two	Pan head slotted machine screw	0640MSP	
63	Three	Round head slotted machine screw	1406MSP	
64	Eight	Flat head socket bolt	3720CSFL	
65	Three	Socket head bolt	5032CSP	
66	One	Socket shoulder bolt	3740SS	
67	Four	Carriage bolt	1424C	
68	Four	Carriage bolt	3736C	
69	Four	Carriage bolt	5024C	
70	Two	Hex head bolt	1410MH	
71	Four	Hex head cap bolt	3724CH2	
72	Four	Hex head cap bolt	5024CH2	
73	Four	Hex jam nut	37NJ	
74	Eight	Hex nut	50NF	
75	Two	Serrated flange hex nut	06NR	
76	Three	Serrated flange hex nut	08NR	
77	Ten	Serrated flange hex nut	14NR	
78	Four	Serrated flange hex nut	31NR	
79	13	Serrated flange hex nut	37NR	
80	Two	Elastic stop nut	50NS	
81	Six	Wing nut	14NWC	
82	Two	Flat washer	06WSAE	
83	Six	Flat washer	14WSAE	
84	Two	Flat washer	50WSAE	
85	Two	Flat washer	75WSAE	
86	Seven	Lock washer	37WS	
87	Eight	Lock washer	50WS	
88	Four	Brass washer	936	
89	Five	Plastic stand off	PSO-14	
90	Two	Rivet	SD-46BS	

