



NOTE: ADD JUMPER TO COM AND STOP TERMINALS IF NO STOP BUTTON IS USED.

WIRED FOR
115V, 1Ø

PowerMaster	
FOR USE WITH: MG, H,J,T OPERATOR WITH CDOMCB BOARD AND CONTACTOR PSC MOTOR	
DATE: 6/30/06	REV. 1
BY: F.S.	MG, H, J, T
CONTROL WIRING DIAGRAM	
WIRING DIAGRAM 6502	
© Copyright PowerMaster 2006 No portion of this diagram may be reproduced without the expressed written permission of the manufacturer.	

INTERNAL INTERLOCK WHEN REQUIRED (BREAKS CIRCUIT WHEN ACTIVATED)

